Power Rust Stop is a white, rust inhibiting, 100% acrylic **COVERAGE** latex direct-to-metal (DTM) coating for use on ferrous metal, galvanized metal and other surfaces exposed to general industrial and atmospheric conditions. Power Rust Stop has excellent aliphatic solvent and water resistance and excellent resistance to most alkalies, detergents and mild acids. This acrylic latex DTM coating does not contain the flammable solvents found in other rust inhibiting paints.

SURFACE PREPARATION

Warning! If you scrape, sand, or remove old paint from any surface, you may release lead dust. LEAD IS TOXIC. Clean tools and drippings with warm soapy water EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Carefully clean up with a wet mop or HEPA vacuum. Before you start, find out how to protect yourself and your family by contacting the U.S. EPA/Lead Information Hotline at 1-800-424-LEAD (5323) or log on to www.epa.gov/lead.

Remove all oil, grease, dirt, loose or scaling paint, rust, mil scale and other foreign matter.

FERROUS METAL: Industrial structures, tank exteriors, structural steel, etc., should be "commercial" blast cleaned (SSPC-SP6) or power tool cleaned (SSPC-SP3) as an alternative.

GALVANIZED METAL, ALUMINUM: Surface oil should be wiped off with mineral spirits and a clean rag.

PREVIOUSLY PAINTED SURFACES: Prepare ruptured or scratched surfaces as for unfinished metal. Spot prime bare ferrous metal as conditions dictate.

APPLICATION TOOLS

Apply Power Rust Stop with brush, roller or airless spray equipment.

Brush: Synthetic, nylon or polyester bristle Roller: Synthetic fiber 3/8" nap or longer Spray: .017 to .021 tip @ 2300-2800 P.S.I.

PRODUCT APPLICATION

Stir thoroughly with a lifting action to fully incorporate; pigments. Power Rust Stop is supplied at application consistency, but can be thinned sparingly with up to 8 oz. of water per gallon to improve application consistency if necessary. Apply with appropriate application equipment. Apply 2 coats of Power Rust Stop. Finish coat will seal spots of 'flash rusting' which may appear on ferrous metal after first coat.

Smooth Surfaces: 400-500 ft²/gal. Porous Surfaces: 100-300 ft²/gal.

Depends on thickness and porosity of the material

DRYING TIME @ 70°F 50% R.H

To Touch: 1 hour

Recoat with Power Rust Stop: 4 hours

Recoat with other water-based coatings: 8 hours

Full Cure: 10 days

CLEANUP

before Power Rust Stop dries. Dispose of waste according to all existing local, state and federal regulations.

PRECAUTIONS

Store in a dry place at temperatures between 40°F (4.5°C) and 90°F (32°C). Keep closures tight and containers upright to prevent leakage. Product is non-combustible. Surface and air temperature must be 50°F or above during application and drying time. Do not recoat with coatings using aromatic or other strong solvents. Do not intermix with solvent base primers or finishes. Do not use Power Rust Stop when rain is imminent or when the dew point is above 60 percent. Power Rust Stop is not designed for tank interiors or for immersion service. When applying with a sprayer, wear a NIOSH approved respirator with any R, P, N or HE filter. The coating and any contaminated diking material should be thoroughly air dried and collected into drums. The drums should be sealed and labeled and land-filled or incinerated according to local, regional and national regulations.



Professional Products **Professional Results**



POWER RUST STOP

100% Acrylic **Rust-Inhibiting Primer**

- Stops flash rusting before it starts
- Fast drying

- Water based formula
- Excellent resistance to most alkalis

NET CONTENTS: 5 Gallons

For Professional Use Only

White



CAUTION! KEEP OUT OF REACH OF CHILDREN.

Do not take internally. Close container after each use. Keep from freezing. Store between 40°F (4.5°C) and 90°F (32°C) 24 hour Emergency "CHEM-TEL" Phone: 1-800-255-3924

Calculated VOC: 98 g/l

FIBERLOCK POWER RUST STOP WHITE 5493 DANGER | DANGER







H319 - Causes serious eve irritation.

H317 - May cause an allergic skin reaction.

H350 - May cause cancer.

H411 - Toxic to aquatic life with long lasting effects.

Obtain special instructions before use.; Wear protective gloves/protective clothing/eye protection/face protection.; Use personal protective equipment as required.; Avoid breathing mist/vapours/spray.; Avoid release to the environment.; Contaminated work clothing should not be allowed out of the workplace.; See SDS for full list of P phrases

IF exposed or concerned: Get medical advice/attention.; Specific treatment (see advice on this label): Wash contaminated clothing before reuse.: IF ON SKIN: Wash with plenty of soap and water.; IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.: If skin irritation or rash occurs: Get medical advice/attention.; See SDS for full list of P phrases

Canadian Contact Info: 4050-B Sladeview Crescent Suite 200 Mississauga, ON L5L 5Y5 Canada

WARNING: Cancer and Reproductive Harm www.P65Warnings.ca.gov

H319 - Provoque une sévère irritation des veux.

H317 - Peut provoquer une allergie cutanée.

H350 - Peut provoquer le cancer.

H411 - Toxique pour les organismes aquatiques, entraîne des effets néfastes à long terme.

Se procurer les instructions avant utilisation.|Porter des gants de protection/des vêtements de protection/un équipement de protection des yeux/du visage.|Utiliser l'équipement de protection individuel requis.|Éviter de respirer les brouillards/ vapeurs/aérosols. lÉviter le reiet dans l'environnement. Les vêtements de travail contaminés ne devraient pas sortir du lieu

SDS pour la liste complète des phrases P

EN CAS d'exposition prouvée ou suspectée: Consulter un médecin.|Traitement spécifique (voir les conseils sur cette étiquette).|Laver les vêtements contaminés avant réutilisation.|EN CAS DE CONTACT AVEC LA PEAU: laver abondamment à l'eau et au savon. EN CAS DE CONTACT AVEC LES YEUX: rincer avec précaution à l'eau pendant plusieurs minutes. Enlever les lentilles de contact si la victime en porte et si elles peuvent être facilement enlevées. Continuer à rincer. En cas d'irritation ou d'éruption cutanée: consulter un médecin. Voir SDS pour la liste complète des phrases P

For Technical Information call 800,342,3755

These suggestions and data are based on information we believe to be reliable. They are offered in good faith, but without guarantee, as conditions and methods of use of this product are beyond our control. Neither ICP Construction, Inc., nor its agents shall be responsible for the use of this product or any procedures or apparatus mentioned. We recommend that the prospective user determine the suitability of, for each specific project and for the health and safety of personnel working in the area.

For additional information check Safety Data Sheet (SDS) or Product Data Sheet (PDS) available online at www.fiberlock.com.

Power Rust Stop™, the Power Rust Stop™ Logo and other marks on this label are trademarks of ICP Construction, Inc.

5493-5

150 Dascomb Rd. Andover, MA 01810 (800) 342-3755 www.fiberlock.com Rev. 10.17.18

Industrial Coatings & Primers