Piranha NexStrip 8 is a self skinning caustic paste paint stripper that can liquefy up to 30 layers of paint on a variety of substrates. Piranha NexStrip 8 has an easy-to-apply, buttery-smooth texture that makes application easy. Piranha NexStrip 8 removes most paints, varnishes, and latex paints from metal, stone, concrete, brick, wood and plaster.

Ideal for multi-layer paint systems, Piranha NexStrip 8 is particularly well suited for stripping lead-based paints (including red lead primer) from painted steel structures. Surfaces must be neutralized after using Piranha NexStrip 8.

NOTE: SURFACES MUST BE NEUTRALIZED AFTER USING PIRANHA NEXSTRIP 8. TO NEUTRALIZE USE PIRANHA NEUTRALIZER (PART # 5710). FAILURE TO PROPERLY NEUTRALIZE SURFACES TREATED WITH PIRANHA NEXSTRIP 8 CAN RESULT IN SUBSEQUENT COATING FAILURE OR RESULT IN A HAZY RESIDUE ON EXPOSED SURFACES!

#### SURFACE PREPARATION

Warning! If you scrape, sand, or remove old paint from any surface, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN, PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE, Wear a NIOSH approved respirator to control lead exposure. Carefully clean up with a wet mop or HEPA vacuum. Before you start, find out how to protect yourself and your family by contacting the U.S. EPA/Lead Information Hotline at 1-800- 424-LEAD (5323) or log on to www.epa.gov/lead.

Protect all surfaces not being stripped with polyethylene sheeting. Protect plants and vegetation.

#### APPLICATION

Key Considerations: Piranha NexStrip 8 is not well suited to alkali resistant paints such as epoxies, urethanes and cementitious paints. neutralization. Before general use, it is imperative to test on a small, inconspicuous area to determine compatibility, required dwell time, coverage and NEUTRALIZATION desired results. The end user shall determine suitability of the product for its intended use(s), and the user assumes all risk and liability whatsoever, NOTE: Piranha NexStrip 8 will darken wood surfaces. Do not use on aluminum, magnesium and other soft metals.

Piranha NexStrip 8 is a ready to use product. Do not dilute. Mix before using for best results. Ideal working temperature is between 60-90°F; when applied at surface temperatures below 55°F performance will be reduced and longer dwell times may be required. Higher temperatures can dry out remover prematurely. Avoid direct sunlight. Workers must wear impervious gloves, apron and footwear and safety goggles and/or faceshield while using process until the pH is permanently altered. When washing off or Piranha NexStrip 8. Take wind drift into consideration if spraying. Before application, it is imperative to test on a small, inconspicuous area to determine compatibility, required dwell time, coverage polyethylene sheeting and masking tape. and desired results. The end user shall determine suitability of the product for its intended use(s), and the user assumes all risk **PRECAUTIONS** and liability whatsoever in connection with the application of this product. Note that the dwell time required to remove a paint system is dependent on the application temperature, humidity and the and clothing. Do not breathe vapors or mists. Wear safety goggles thickness/type of paint system being stripped. Typically 12-14 hour with faceshield, impervious gloves and impervious, protective dwell times will yield good results for multi-layer painted substrates. However, extended dwell times of 24 to 72 hours can result in more Use only with adequate ventilation. Wash with soap and water after complete outcomes. When Piranha NexStrip 8 is to be left for an each use. Keep container tightly closed when not in use. Store in a dry, extended period of time (beyond 8 hours), cover with Piranha Paper to slow the evaporation process and extend the product dwell time.

## **APPLICATION TOOLS**

airless spray equipment.

Brush: Synthetic, nylon or polyester bristle

Spray: Specialized spray equipment required. Contact Fiberlock Technologies for detailed sprayer application information.

#### COVERAGE

Dependent on application thickness:

1/4'' = 6.4 ft<sup>2</sup> per gallon  $1/8'' = 12.8 \, \text{ft}^2 \, \text{per gallon}$ 1/16" = 25.6 ft<sup>2</sup> per gallon

Coverage rates will vary depending upon surface and application method. Be certain that all uneven or irregular surfaces receive adequate coverage

# CLEANUP

Once the paint has fully softened and lifted, remove using a scraper or putty knife. Collect all remover waste and paint residue for proper disposal. Dispose of contents and container in accordance with local and national regulations. Do not store or collect removed paint or residue in metal containers. Use plastic containers only. Once all bulk residues have been removed do not let any remaining residues dry. Immediately following paint removal thoroughly clean substrate with mild detergent solution. If there is a thin layer of paint residue that remains agitation with a nylon bristle brush or pressure washing will often remove this layer. This step is critical when removing red lead primers as the primer will only be fully removed during the final washing and rinsing steps. If allowed to dry the residue will re-harden and the Piranha NexStrip 8 stripper will need to be reapplied. Perform a final clean water rinse and let surface fully dry for at least 24 hours before proceeding to

This is a critical step before repainting. If the substrate is not properly neutralized then the new coating system will likely fail. Apply Piranha Neutralizer (Part #5710) according to the directions on the packaging. After neutralizing, test the substrate using pH paperto determine the approximate pH of the substrate. Once the substrate has been sufficiently neutralized (pH of 6-8) allow substrate to fully dry and retest pH. It is important to retest the substrate after it has dried to ensure that no additional residues have "bled" out of the substrate and recontaminated the surface. If the substrate pH test reading is high then repeat the neutralization scraping off Piranha 8 be careful not to come in contact with items that are sensitive to high alkalinity. Protect unaffected areas with

DANGER: Corrosive. Causes severe eye and skin burns. Contains hydrated lime and sodium hydroxide. Prevent contact with eyes, skin clothing and footwear when using this product. Do not take internally. well-ventilated place at temperatures between 40°F (4.5°C) and 90°F (32°C). Store in corrosive resistant container with a corrosive resistant inner liner.

Apply Piranha NexStrip 8 with a brush, trowel or specially designed MARNING: Cancer and Reproductive Harm www.P65Warnings.ca.gov





# **Extreme Duty Self Skinning Caustic Paint Remover**

- Ideal for use on red lead primer
- Super strength self skinning caustic formula
- Tears through over 30 layers
- of paint
- Easy to apply

# NET CONTENTS: 5 Gallons

For Professional Use Only

Paint Removal Products

# **FIRST AID**

EYES: Immediately flush thoroughly with water for at least 30 minutes. Hold eyelids open to assure the eyes are thoroughly flushed. Get immediate medical attention.

SKIN: Immediately remove contaminated clothing and shoes while flushing skin with water for at least 20 minutes. Then wash skin with soap and water. Get medical attention. Launder contaminated clothing before reuse. Discard shoes.

INHALATION: Move to fresh air. If breathing has stopped, give artificial respiration. Get immediate medical attention.

INGESTION: If swallowed and conscious, immediately rinse mouth with water and give 1 glass of water. Do not induce vomiting. Immediately contact poison control center, physician or hospital emergency room for instructions.

# DANGER! **KEEP OUT OF REACH OF CHILDREN.**

## FOR PROFESSIONAL APPLICATORS ONLY!

Do not take internally. Close container after each use. Keep from freezing. Store between 40°F (4.5°C) and 90°F (32°C). 24 hour Emergency "CHEM-TEL" - 1-800-255-3924

# **FIBERLOCK PIRANHA NEXSTRIP 8 5702 DANGER | DANGER**



H290 - May be corrosive to metals.

H314 - Causes severe skin burns and eye damage.

H350 - May cause cancer.

H335 - May cause respiratory irritation.

H373 - May cause damage to organs through prolonged or repeated exposure.

Obtain special instructions before use.: Do not breathe dust/fume /gas/mist/vapours/spray.; Use only outdoors or in a well-ventilated area.; Wear protective gloves/protective clothing/eye protection/face protection.; Use personal protective equipment as required.; Keep only in original container.; See SDS for full list of P phrases

IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.: IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower.: IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.; IF exposed or concerned: Get medical advice/attention.: Immediately call a POISON CENTER or doctor/physician.: Specific treatment (see advice on this label).; See SDS for full list of P phrases

#### Canadian Contact Info 4050-B Sladeview Crescent Suite 200 Mississauga, ON L5L 5Y5 Canada

#### For Technical Information call 800.342.3755

H290 - Peut être corrosif pour les métaux. H314 - Provoque des brûlures de la peau et des lésions oculaires graves. H350 - Peut provoquer le cancer. H335 - Peut irriter les voies respiratoires. H373 - Risque présumé d'effets graves pour les organes à la suite

d'expositions répétées ou d'une exposition prolongée.

Se procurer les instructions avant utilisation. Ne pas respirer les poussières/ fumées/gaz/brouillards/vapeurs/aérosols. Utiliser seulement en plein air ou dans un endroit bien ventilé.|Porter des gants de protection/des vêtements de protection/un équipement de protection des yeux/du visage.|Utiliser l'équipement de protection individuel requis.|Conserver uniquement dans le récipient d'origine. Voir SDS pour la liste complète des phrases P

EN CAS D'INGESTION: rincer la bouche. NE PAS faire vomir. EN CAS DE CONTACT AVEC LA PEAU (ou les cheveux): enlever immédiatement les vêtements contaminés. Rincer la peau à l'eau/ se doucher. EN CAS DE CONTACT AVEC LES YEUX: rincer avec précaution à l'eau pendant plusieurs minutes. Enlever les lentilles de contact si la victime en porte et si elles peuvent être facilement enlevées. Continuer à rincer. IEN CAS d'exposition prouvée ou suspectée: Consulter un médecin. Appeler immédiatement un CENTRE ANTIPOISON ou un médecin.|Traitement spécifique (voir les conseils sur cette étiquette).|Voir SDS pour la liste complète des phrases P

These suggestions and data are based on information we believe to be reliable. They are offered in good faith, but without guarantee, as conditions and methods of use of this product are beyond our control. Neither ICP Construction, Inc., nor its agents shall be responsible for the use of this product or any procedures or apparatus mentioned. We recommend that the prospective user determine the suitability of Piranha NexStrip 8, for each specific project and for the health and safety of personnel working in the area.

For additional information check Safety Data Sheet (SDS) or Product Data Sheet (PDS) available online at www.fiberlock.com.

Piranha NexStrip 8, the Piranha NexStrip 8 Logo and other marks on this label are trademarks of ICP Construction, Inc.



150 Dascomb Rd. Andover, MA 01810 (800) 342-3755 www.fiberlock.com Rev. 10.17.18



